



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D2594-1

Job Sheet 201243



Part No: D2594-1

Job Qty: 100 pcs

Part Name: Plug



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 9/27/19

Job Tracking No:

Due Date: 10/25/19

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: DWG REV C IPP D 02.08.22 Make in Cobra KJ IPP E 06.12.11 ecn 836 EC

Shp Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Hardinge - 1	100 pcs	10/25/19	10/25/19	0.01	2.87	Hardinge - 1		BM 14-11-01
110	QC 2	100 pcs	10/25/19	10/25/19	0.00	0.00	QC 2 - 1		
							QC 2 - 12		
							QC 2 - 14		
							QC 2 - 17		
							QC 2 - 19		
							QC 2 - 2		
							QC 2 - 20		
							QC 2 - 22		
							QC 2 - 23		
							QC 2 - 25		
							QC 2 - 32		
							QC 2 - 33		
							QC 2 - 35		
							QC 2 - 39		
							QC 2 - 4		
							QC 2 - 40		
							QC 2 - 44		
							QC 2 - 45		
							QC 2 - 48		
							QC 2 - 49		
							QC 2 - 50		
							QC 2 - 51		
							QC 2 - 52		
							QC 2 - 57		
							QC 2 - 62		
							QC 2 - 63		
							QC 2 - 8		
							QC 2 - 66		
							QC 2 - 64		



Container No: S229062



Part: D2594-1

Job No: 201243

Serial No/Batch: S229062

Revision:

Inspector:

Exp Date:

Instructions: Various STC's

Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
Tel.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Date: 11/01/19

Plex 9/27/19 1:27 PM Dart.lajeunesse.marie

120 QC 8	100 pcs	10/25/19	0.00 0.00	QC 2 - 65	
				QC 2 - 5	
				QC 2 - 71	
				QC 2 - 73	
				QC 2 - 69	
				QC 8 - 12	
				QC 8 - 14	
				QC 8 - 17	
				QC 8 - 20	
				QC 8 - 25	
				QC 8 - 3	
				QC 8 - 32	
				QC 8 - 33	
				QC 8 - 35	
				QC 8 - 39	
				QC 8 - 4	
				QC 8 - 44	
				QC 8 - 45	
				QC 8 - 49	
				QC 8 - 58	
				QC 8 - 8	
				QC 8 - 9	
				QC 8 - 68	
				QC 8 - 67	
				QC 8 - 1 (A)	
				QC 8 - 47	
				QC 8 - 40	
				QC 8 - 52	
				QC 8 - 23	
				QC 8 - 57	
				QC 8 - 76	
				QC 8 - 61	
130 Handfinish - 1-1 Chemical- B4B	100 pcs	10/25/19	0.00 0.23	Handfinish - 1 - 1 - B4B	
				Handfinish - 1 - 2 - B4B	
				Handfinish - 1 - 3 - B4B	NOV 08 2019
				Handfinish - 1 - 4 - B4B	
				Handfinish - 1 - 5 - B4B	
				Handfinish - 1 - 6 - B4B	
				Handfinish - 1 - 7 - B4B	
				Handfinish - 1 - 8 - B4B	
				Handfinish - 1 - 9 - B4B	
				Handfinish - 1 - 10 - B4B	
				Handfinish - 1 - 11 - B4B	
				Handfinish - 1 - 12 - B4B	
				Handfinish - 1 - 13 - B4B	
				Handfinish - 1 - 14 - B4B	
				Handfinish - 1 - 15 - B4B	

Plex 9/27/19 1:27 PM Dart.lajeunesse.marie

Plex 9/27/19 1:27 PM Dart.lajeunesse.marie

				B4B	
				Packaging 3 - 16 - B4B	
				Packaging 3 - 17 - B4B	
				Packaging 3 - 18 - B4B	
				Packaging 3 - 19 - B4B	
				Packaging 3 - 20 - B4B	
				Packaging 3 - 21 - B4B	
				Packaging 3 - 22 - B4B	
				Packaging 3 - 23 - B4B	
				Packaging 3 - 24 - B4B	
				Packaging 3 - 25 - B4B	
				Packaging 3 - 26 - B4B	
				Packaging 3 - 27 - B4B	
				Packaging 3 - 28 - B4B	
				Packaging 3 - 29 - B4B	
				Packaging 3 - 30 - B4B	
				Packaging 3 - 31 - B4B	
				Packaging 3 - 32 - B4B	
				Packaging 3 - 33 - B4B	
				Packaging 3 - 34 - B4B	
				Packaging 3 - 35 - B4B	
				Packaging 3 - 36 - B4B	
170 QC 21 - SA	100 pcs	10/25/19	0.00 0.00	QC 21 - SA - 21	DAS 21 NOV 15 2019
				QC 21 - SA - 70	
				QC 21 - SA - 53	

Part Op 100 - (Hardinge) 1-Make as per Dwg D2594-1 and Folio FA262.
 Descriptions: 110 - (QC2- Inspect parts off machine FA/FAIB)
 120 - (QC8- Inspect parts - second check)
 130 - (Chemical Conversion Coat per QSI005 4.1)
 135 - (White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum) START TIME: _____
 150 - (QC3- Inspect Part Finish)
 160 - (Identify as per dwg & Stock Location: _____) LOCATION .
 170 - (QC21- Final Inspection - Work Order Release)

M6061T6R0.625
 S226375
 M6061T6R0.625
 S214490

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
M6061T6R0.625	6061-T6 Round Bar .625"	5.2100 ft (.0521 ea)	100-Hardinge - 1	S226375 S214490

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
100-Hardinge - 1	M6061T6R0.625	5	30	0

Part Specifications					
Spec No	Description	Target/Tolerance	Limits	Type	Special Comments
1	Plug	0.060inches $\pm$ 0.005	0.065 0.055	0.059	
2	Plug	0.500inches $\pm$ 0.010	0.510 0.490	0.500	
3	Plug	0.625inches $\pm$ 0.010	0.635 0.615	0.624	
4	Plug	0.430inches + 0.000 - 0.002	0.430 0.428	0.429	
5	Plug	0.090inches + 0.000 - 0.002	0.090 0.088	0.089	
6	Plug	0.045inches + 0.000 - 0.002	0.045 0.043	0.045	

Plex 9/27/19 1:27 PM Dart.lajeunesse.marie

Entered: _____ Date: _____

WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐



Job: _____ Part No. _____		DISPOSITION Rework ☐ ☐ ☐ Scrap ☐ ☐ ☐ Use-as-is ☐ ☐ ☐			DEPARTMENT/PROCESS Skid-tube ☐ ☐ ☐ ☐ ☐ Machining ☐ ☐ ☐ ☐ ☐ Large Fab ☐ ☐ ☐ ☐ ☐ Cross tube ☐ ☐ ☐ ☐ ☐ Small Fab ☐ ☐ ☐ ☐ ☐ Finishing ☐ ☐ ☐ ☐ ☐ Eng. (Non-AW) ☐ ☐ ☐ ☐ ☐ Prod. Eng. Coord. ☐ ☐ ☐ ☐ ☐ Rec/Store/Packaging ☐ ☐ ☐ ☐ ☐ Engineering ☐ ☐ ☐ ☐ ☐ Water Jet ☐ ☐ ☐ ☐ ☐ Supplier ☐ ☐ ☐ ☐ ☐ Quality ☐ ☐ ☐ ☐ ☐			MRB (QS1042) ☐ ☐ ☐ ☐ ☐																																																																							
Date : _____		Sequence #: _____		QTY Affected : _____		MRB (QS1042) ☐ ☐ ☐ ☐ ☐																																																																									
Description Work Order Deviation				Disposition																																																																											
Root Cause <table border="1"> <tr> <td>Operator</td> <td>☐</td> </tr> <tr> <td>Manufacturing Process</td> <td>☐</td> </tr> <tr> <td>Equip/Tooling</td> <td>☐</td> </tr> <tr> <td>Handling/Preservation</td> <td>☐</td> </tr> <tr> <td>Material</td> <td>☐</td> </tr> <tr> <td>Product Improvement</td> <td>☐</td> </tr> <tr> <td>Process Improvement</td> <td>☐</td> </tr> <tr> <td>Human Factors</td> <td>☐</td> </tr> </table>				Operator	☐	Manufacturing Process	☐	Equip/Tooling	☐	Handling/Preservation	☐	Material	☐	Product Improvement	☐	Process Improvement	☐	Human Factors	☐	FAULT CATEGORY <table border="1"> <tr> <td>Pressure/Forced</td> <td>☐</td> <td>Contamination</td> <td>☐</td> <td>Power Loss/Surge</td> <td>☐</td> <td>Positioned Wrong</td> <td>☐</td> </tr> <tr> <td>Bending</td> <td>☐</td> <td>Misaligned/off center</td> <td>☐</td> <td>Folio/Program</td> <td>☐</td> <td>Outside Tolerance</td> <td>☐</td> </tr> <tr> <td>Crushing</td> <td>☐</td> <td>BOM/Route</td> <td>☐</td> <td>Grain Direction</td> <td>☐</td> <td>Drawing</td> <td>☐</td> </tr> <tr> <td>Cracks</td> <td>☐</td> <td>Broken/Damage/Defect</td> <td>☐</td> <td>Weld</td> <td>☐</td> <td>Finish</td> <td>☐</td> </tr> <tr> <td>Crimp/Kink/Ripple/Wave/Twist</td> <td>☐</td> <td>Incomplete/Unclear Instructions</td> <td>☐</td> <td>Wrong Stock Pulled</td> <td>☐</td> <td>Part Lost/Missing</td> <td>☐</td> </tr> <tr> <td>Marks/Chatter</td> <td>☐</td> <td>Drill Holes</td> <td>☐</td> <td>Out of Sequence</td> <td>☐</td> <td>Misread</td> <td>☐</td> </tr> <tr> <td>Mislabeled</td> <td>☐</td> <td>Fit/Function</td> <td>☐</td> <td>Off-set/Set-up</td> <td>☐</td> <td></td> <td></td> </tr> </table>				Pressure/Forced	☐	Contamination	☐	Power Loss/Surge	☐	Positioned Wrong	☐	Bending	☐	Misaligned/off center	☐	Folio/Program	☐	Outside Tolerance	☐	Crushing	☐	BOM/Route	☐	Grain Direction	☐	Drawing	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Finish	☐	Crimp/Kink/Ripple/Wave/Twist	☐	Incomplete/Unclear Instructions	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐	Marks/Chatter	☐	Drill Holes	☐	Out of Sequence	☐	Misread	☐	Mislabeled	☐	Fit/Function	☐	Off-set/Set-up	☐		
				Operator	☐																																																																										
				Manufacturing Process	☐																																																																										
				Equip/Tooling	☐																																																																										
Handling/Preservation	☐																																																																														
Material	☐																																																																														
Product Improvement	☐																																																																														
Process Improvement	☐																																																																														
Human Factors	☐																																																																														
Pressure/Forced	☐	Contamination	☐	Power Loss/Surge	☐	Positioned Wrong	☐																																																																								
Bending	☐	Misaligned/off center	☐	Folio/Program	☐	Outside Tolerance	☐																																																																								
Crushing	☐	BOM/Route	☐	Grain Direction	☐	Drawing	☐																																																																								
Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Finish	☐																																																																								
Crimp/Kink/Ripple/Wave/Twist	☐	Incomplete/Unclear Instructions	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐																																																																								
Marks/Chatter	☐	Drill Holes	☐	Out of Sequence	☐	Misread	☐																																																																								
Mislabeled	☐	Fit/Function	☐	Off-set/Set-up	☐																																																																										
Other/Details: _____																																																																															
Completed By _____				Lead hand / Supervisor _____																																																																											
QC / QA Coordinator _____				QC / QA Coordinator _____																																																																											